

KUIPER DAIRY LAGOON TREATMENT



Before BioFlora Treatment

Photo taken 12-26-95. Solids covered most of lagoon causing poor waste treatment and bad odors.



After BioFlora Treatment

Photo taken 3-14-96 after 78 days treatment. Floating sludge and odors significantly reduced. A noted increase in solids digestion from bottom of lagoon was observed.