

# Lake Treatment Comparisons—Big Elk Meadows 8/03

These photos were taken of different lakes. In the Spring of 2003 Big Elk Meadow treated four of the six lakes with Biological Solutions Products. One of the lakes that remained untreated has had a working aerator on the lake for two years and has a severe algae bloom. (Photo 6). The largest lake that remained untreated is now anaerobic with a severe algae bloom. The treated lakes are healthy and do not have any odors connected to either an anaerobic environment or algae blooms.



**Photo 1: Treated—no aerator  
Willow Lake**



**Photo 2: Untreated—algae &  
anaerobic environment  
Meadow Lake**



**Photo 3: Shoreline  
Treated—Mirror Lake**



**Photo 4: Shoreline Untreated –  
Anaerobic—Meadow Lake**



**Photo 5: After Treatment—with  
aerator— Sunset Lake**



**Photo 6: Pretreatment—with  
aerator—algae bloom  
Sunset Lake**